



EMERGENCY - EXIT LIGHT TEST RESULTS

Company BE SMART ELECTRICAL

Test Date 01/01/2008

Address PO BOX 545
KALLANGUR , QLD,4503

Items Passed 14

Items Failed NIL ALL WERE REPAIRED

Light No	Location	Light Description	Mains Result	Discharge Result	Retest Date	Action	Comment
1	OFFICE	SPITFIRE 10 WATT EMERGENCY LIGHT	PASS	PASS	07/01/2008		
2	OFFICE	SPITFIRE 10 WATT EMERGENCY LIGHT	PASS	PASS	07/01/2008		
3	OFFICE	SPITFIRE 10 WATT EMERGENCY LIGHT	PASS	FAIL	07/01/2008	TEST FAILED / NEW BATTERY	PASSED TEST
4	OFFICE	SPITFIRE 10 WATT EMERGENCY LIGHT	PASS	PASS	07/01/2008		
5	OFFICE	SPITFIRE 10 WATT EMERGENCY LIGHT	PASS	PASS	07/01/2008		
6	OFFICE	SPITFIRE 10 WATT EMERGENCY LIGHT	PASS	PASS	07/01/2008		
7	OFFICE	SPITFIRE 10 WATT EMERGENCY LIGHT	PASS	PASS	07/01/2008		
8	OFFICE	SPITFIRE 10 WATT EMERGENCY LIGHT	PASS	PASS	07/01/2008		
9	OFFICE	BARDIC 10 WATT EXIT LIGHT	PASS	FAIL	07/01/2008	TUBE OUT / NEW TUBE FITTED	PASSED TEST
10	OFFICE	BARDIC 10 WATT EXIT LIGHT	PASS	PASS	07/01/2008		
11	OFFICE	BARDIC 10 WATT EXIT LIGHT	PASS	PASS	07/01/2008		
12	OFFICE	BARDIC 10 WATT EXIT LIGHT	PASS	PASS	07/01/2008		
13	OFFICE	BARDIC 10 WATT EXIT LIGHT	PASS	PASS	07/01/2008		
14	OFFICE	BARDIC 10 WATT EXIT LIGHT	PASS	PASS	07/01/2008		